

Quality Assurance Handbook (Products)
Product Category 2.1 Work Wear (WWS), 1.11.2018/31.8.2015
Supporting Material
Packaging Instructions Garments, (overseas) 2.1 - 5.2_1

These general instructions are to be applied to all deliveries of garments to Lindström Group. If required these instructions are supplemented with separate product specific instructions.

The goods are to be packed into durable boxes to ensure that the package endures the normal exertions caused during transportation and handling.

The box size is defined to be 400 x 600 x 320 or 400 x 300 x 320. (mm)

Packing:



A box is filled by using two piles.



Box is fully loaded.



Box is tightened with two durable bands on the same side.

Lindström Oy			
Purchase order nr:	58177		
Product code:	8026	Size:	54
Amount (pcs/box):	40		
Consecutive nr / Total:	1 / 27		
Controller:			

The boxes shall be marked as above. The marking shall be visible from the direction of unloading. I.e. the marking is to be printed on both the short and the long side of the box.

Container is loaded from the floor to the roof as per picture below. 7 layers of 320 mm boxes can be fitted in a container.

In case the container is not filled up to 100 % the boxes shall be loaded so that the risk for them to collapse during the transport in the container is prevented.

